




.2/20








Time





Reduction temperature (°C)

















Fig. 12



STEP I: reduction of the outer oxide layer with heating from the metal





STEP II: reduction of the oxide with heating from the metal and from the sponge iron




STEP III: final reduction of the oxide with heating from the sponge iron


Thermal flow
× × Current lines









14/20





16/20








FIG. 19




Recycling flow rate

Recycling flow rate with fixed dew point



Reactor dew point






Fig. 22

FIG. 23

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.